

Memo

To: Randy Lyman
From: Gene Pabst
Date: February 7, 2000
Subject: Septic tank at Yarbrough's Machine Shop

On February 7, 2000 (11:00 A.M.) I contacted Mr. Rusty Reynaud, owner of Yarbrough's Machine Shop, to inquire about their septic tank being pumped out on January 20, 2000. Mr. Reynaud explained that the front building is on septic tank and the building in the back is connected to the sanitary sewer. I told Mr. Raynaud that we were concerned about what might be discharged to septic tank and then taken to the treatment plant. In both buildings there is only restrooms. In the back building they manufacture pallet stackers. They do have a paint booth. This is a dry operation. They wipe the parts off before they paint them. Mr. Raynaud said that when they started this operation that he did have someone that wanted to sell him a phosphatizing operation, but he was not to interested because of the water aspect and having a wet product that needed to be painted. I explained a little about what he would have been into if he would have gone with the phosphatizing operation. We then went to the front building. This building has been added onto twice. The front part of the building has bathrooms only that go to their septic tank. When they did their first addition they built over the septic tank and now it is inside the building. They have a steel plate, approximately 1' x1', over the access to the septic tank. In this part of the building there is only restrooms. When they added on the second time, the new addition was originally supposed to be a warehouse but was changed to be part of their machine shop. The only wet operation in this part of the building is a sink. This appears to connect to the bathroom in the first addition.

They do have a parts washer in each building and they are serviced through Superior Solvents.

Mr. Raynaud said that they have a low flow toilet in the bathroom in the original building. Since there is not enough water to flow the solids to the septic tank the line backs up. When they call a plumber out to clean out the line, then he always tells them that they need to clean out their septic tank.

I saw nothing in these two buildings, at the present time, that would be cause for concern.

Mr. Raynaud is paying a sewer bill on both buildings.

514 N. Fremont

0105006000 CY 01 BK 1
0105-0060-00 REYNAUD GARY 514
DBA YARBOROUGH'S MACHINE CO
514 N FREMONT
SPRINGFIELD MO 65802-3532

2/ 7/00 12:54:27

A 65802

PUBLISH: YES

ACCOUNT STATUS 01
SVCS PRES 11 12 21 31 00 00 00 SW
NUMBER SVCS SIGNED FOR 4
SPECIAL HANDLING CODE
PREVIOUS CHANGE TYPE 114
TRANSFER AMOUNT \$.00
MAINTENANCE DATE 11/20/87
NO AUTO DISCONNECTS 0
CURRENT ACCOUNT ENTRY
CURRENT AEF DATE 2/1988
CURTAILMENT CODE 1
PHONE 417 883-1022

INITIAL DATE 11/20/87
NUMBER OF ACTIVE SERVICES 4
AUTOMATIC CONN CODE
PENALTY INHIBIT CODE
PREVIOUS CHANGE DATE 7/13/99
TAX CLASS CODE 2
TRANSFER ACCT NO
TAX LOCATION Springfield
TRNSF FNL AMT TO ACCTNO
MAP NUMBER NEA03
TOTAL ACCOUNT ENTRY 30.00
S I C
SOCIAL SECURITY NUMBER
PAGER,MOBILE,MSG. #

NOTE R BLDG W IN WEEDS
SPECIAL LOCATION
6'W 4'S FIRE HYDRANT

ROUTE

I

0201109001 CY 01 BK 3
0201-1090-01 REYNAUD GARY

514

N FREMONT

2/ 7/00 12:54:04

65802

PUBLISH: YES

ACCOUNT STATUS 01
SVCS PRES 11 12 21 31 00 00 00 SW
NUMBER SVCS SIGNED FOR 4
SPECIAL HANDLING CODE
PREVIOUS CHANGE TYPE 079
TRANSFER AMOUNT \$.00
MAINTENANCE DATE 0/ 0/00
NO AUTO DISCONNECTS 0
CURRENT ACCOUNT ENTRY
CURRENT AEF DATE 0/0000
CURTAILMENT CODE 2
PHONE

INITIAL DATE 3/13/72
NUMBER OF ACTIVE SERVICES 4
AUTOMATIC CONN CODE
PENALTY INHIBIT CODE
PREVIOUS CHANGE DATE 9/26/97
TAX CLASS CODE 2
TRANSFER FROM ACCT NO 2116-1090-21
TAX LOCATION Springfield
TRNSF FNL AMT TO ACCTNO
MAP NUMBER NEA03
TOTAL ACCOUNT ENTRY
S I C
SOCIAL SECURITY NUMBER
PAGER,MOBILE,MSG. #

ROUTE

I

FROM THE DESK OF 
J. RANDALL LYMAN
PRETREATMENT COORDINATOR
CITY OF SPRINGFIELD
1216 W. NICHOLS ST.
SPRINGFIELD, MISSOURI 65802
PHONE 417-864-1487
Fax 417-864-1918

FEBRUARY 1, 2000

GENE,

PLEASE GET THE MANIFEST THAT BOB WAS REFERRING TO AT YARBROUGH'S MACHINE SHOP AND SEE IF THEY HAVE PROCESS WASTEWATER GOING TO THEIR SEPTIC SYSTEM, I.E. HOT TANK ETC., OR IF THEY ARE HOOKED TO SANITARY SEWER. I BELIEVE HE SAID THE HAULER WAS GREER.

514 N. Fremont

6

7

8

LAST MH & LH NUMBER
N-20

NOTE: IN THIS QUARTER SECTION THIS IS
NO MH WITH MAINT. NUMBER 24.

1

2

3

4

5

6

7

536

522

514

★ 514 N FREMONT

REYNAUD, GARY L

33

34

35

36

37

42

41

40

39

38

13

12

11

8

9

10

FREMONT

14

15

16

17

18

19

20

22

23

24

RESERVE

40

2

21

32

1359

1401

1445